GRCRS Package Cover Sheet

Site Nan	ne Creola Don Residence
Site Ado	Hess 8264 Main St., Pittsville W. #03-72-101980 Date of Closure Decision 11/7-14/97
BRRTS	#03-72-101980 Date of Closure Decision 11/7-14/97
	losure letter(s)
	Groundwater Use Restriction/Warranty Deed
Yes	Off-site contamination present? (Include related documents)
YesNo	Right-of-way contamination present? (Include related documents)
~	General location map
50	9811. 4096396 GPS x-coordinate
44	0646. 0002670 GPS y-coordinate
	Detailed site map(s)
/ (Groundwater flow map(s)
I	Latest map(s) showing extent or outline of plume
	catest table(s) of analytical results (soil results included only if soil deed estriction is incorporated into groundwater use restriction document)
If availa	ble:
I	legal description
Woo.	1 Ct #3/-00336 County and Parcel I.D./Tax Parcel No.
(jeologic cross sections
ı	soconcentrations man(s)

863 ME111

GROUNDWATER USE RESTRICTION

Document Number

Document Title

PT LOT 1, BLK 8, SW-SE 27-23-3, PITTSVILLE CREOLA, DON M ETUX TO WISO CO. WIS.

'98 FEB 23 AM 9 57

VOL. 863 RECPAGE 111
REDISTER OF DEEDS

Recording Area

Name and Return Address 9

DONALD CREOLA 1133 BRIARWOODSST MARSHFIELD, WI 54449 14/00 D

31-00336

Parcel Identification Number (PIN)

Vol. 853 PAGE 112

Legal Description of the Property as it Appears on the Most Recent Deed

Lot 3 of Wood County Certified Survey Map No. 985, being part of Lot 1 of Block 8 of Subdivision of the SW1/4 of SE 1/4 of Section 27, Township 23 North, Range 3 East according to Sargent's Plat of the City of Pittsville, Wood County, Wisconsin. Volume 4, page 85.

Recording Area

Name of Return Address

Delaration of Restrictions

Property Indentification Number (PIN): 31-00336

STATE OF WISCONSIN)
) SS
COUNTY OF WOOD)


WHEREAS, Don M. Creola and Nancy A. Creola are the owners of the above-described property.

WHEREAS, one or more tetrachloroethane discharges have occurred at this property. Tetrachloroethane contaminated groundwater above NR 140 enforcement standards exists on this property at the following location(s): tetrachloroethane (11ppb) at MW-3 and soil contamination exists at the following locations: benzene (76 ppb) at GP3.

WHEREAS, it is the desire and intention of the property owner to impose on the property restrictions which will make it unnecessary to conduct additional soil or groundwater remediation activities on the property at the present time.

WHEREAS, natural attenuation has been approved by the Department of Natural Resources to remediate groundwater exceeding ch. NR 140 groundwater standards within the boundaries of this property.


WHEREAS, construction of wells where the water quality exceeds the drinking water standards in ch. NR 809 is restricted by ch. NR 811 and ch. NR 812. Special well construction standards or water treatment requirements, or both, or well construction prohibitions may apply





7.5 Minute USGS Topographic Map (1984)




		Creolo	Property	SI – Pittsville	e, WI	
			FIGU	RE 1		
		SITE	LOC	ATION	MAP	
	SCALF:	1" = 2000"	•	DATE	09/27/96	
	Environm	ental Compliance	Consultar	its, Inc.	BY: J. Kralick	












TABLE 1 **GROUNDWATER LABORATORY RESULTS CREOLA PROPERTY**

		March	21, 1997		TRIP		July 25	5, 1997		TRIP	NR 140	NR 140
					BLANK					BLANK	PAL	ES
SAMPLE ID	MW-1	MW-2	MW-3	MW-3P		MW-1	MW-2	MW-3	MW-3P			
Analyte												
GRO (mg/l)	0.10	0.10	< 0.029	< 0.038		NA	NA	NA	NA	NA		
Lead (ug/l)	<1.5	<1.5	<1.5	<1.9	NA	<1.5	<1.5	<1.5	NA	NA		
VOCs												
Benzene		0.73	<0.22>	<0.30>			<0.59>				0.5	5
Toluene	<0.38>	<0.53>		<0.67>					<0.58>		68.6	343
Ethylbenzene	0.97	1.1		<0.24>							140	700
1,2,4-Trimethylbenzene	0.88	11		<0.32>		-			<0.81>			
1,3,5-Trimethylbenzene	1.1	4.1		<0.37>					<0.39>			
Methyl-tert-butyl-ether											12	60
m&p Xylenes	2.3	2.6	<0.52>	<0.57>							*124	*620
o-Xylenes	<0.69>	<0,69>		<0.60>							*124	*620
1,2-Dichloroethane		<0.46>	5.2	3.0	NA		0.87	4.0	4.3		0.5	5
Tetrachloroethene		1,2	11	3.7	NA		<0.46>	11	3.0		0.5	5
Trichloroethene		<0.67>	1.6	0.98	NA		<0.23>	1.5	0.98		0.5	5
Other VOCs	YES	YES	YES	YES	NA	YES	YES	YES	YES	YES	-	

	Parameter analyzed, but not detected, MDL < NR 140 ES
100	Parameter concentration exceeds the NR 140 Enforcement Standard (ES)
NA	Parameter not analyzed
<10>	Parameter analyzed but result between MDL and LOQ.

LOQ: Limit of quantitation.

MDL: Method detection limit.

PAL: NR 140 Groundwater Quality Preventative Action Limit. ES: NR 140 Groundwater Quality Enforcement Standard.

* NR 140 standard is for Total Xylenes

FILE GUPT



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Tommy G. Thompson, Governor George E. Meyer, Secretary Scott Humrickhouse, Regional Director Wausau Office 5301 Rib Mountain Drive Wausau, WI 54401 TELEPHONE 715-359-4522 FAX 715-355-5253

November 17, 1997

BRRTS #03-72-101980

MR DON CREOLA 1133 BRIARWOOD MARSHFIELD WI 54449

Subject:

Case Closure Creola Property 8264 Main Street Pittsville, Wisconsin

Dear Mr. Creola:

On June 6, 1996, the Department of Natural Resources provided a notice to you that the degree and extent of petroleum contamination at the above-named site was required to be investigated and remediated. We have since been informed that the required investigation and remediation has been accomplished.

On November 10, 1997, the above-named site was reviewed by the West Central Region Closeout Committee for a determination as to whether or not the case qualified for close out under ch. NR 726, Wisconsin Administrative Code. Based on the investigative documentation provided to the Department, the case could be considered for closure with a groundwater use restriction. The groundwater use restriction is required due to the concentration of tetrachloroethane in the groundwater. This concentration is above the Enforcement Standard in s.NR 140.10 Wis. Adm. Code.

If a groundwater use restriction which meets the requirements of s.NR726.05(8)(am) Wis. Adm. Code, is recorded with the County Register of Deeds, the Department will consider the case closed, having determined that no further action is necessary on the site at this time. I have enclosed a model of the groundwater use restriction. Please complete the form with the needed site-specific information and return it to the Department within 15 days for review. Do not file the document with the County Register of Deeds until the Department has approved the deed attachment. Once a notarized copy of the recorded deed has been received, a final close out letter will be issued for the site.





State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Tommy G. Thompson, Governor George E. Meyer, Secretary Scott Humrickhouse, Regional Director Wausau Office 5301 Rib Mountain Drive Wausau, WI 54401 TELEPHONE 715-359-4522 FAX 715-355-5253

March 10, 1998

BRRTS#:03-72-101980

MR DON CREOLA 115 BRIARWOOD AVENUE MARSHFIELD WI 54449

SUBJECT: Creola Property, 8264 Main Street, Pittsville, WI

Dear Mr. Creola:

On March 9, 1998, the Department of Natural Resources received a copy of the registered groundwater use restriction that was placed on the Creola property in Pittsville, WI as described above. The groundwater use restriction states that tetrachloroethane contaminated groundwater and benzene contamination soil exists on this site. The groundwater use restriction also states natural attenuation has been approved to remediate the groundwater at the property. Based on this restriction and the fact that the monitoring wells have been properly abandoned, you have met the conditions for closure.

Your site is considered closed with no further action necessary. If you have any questions concerning this letter, please call me at (715)359-4522.

Sincerely,

WEST CENTRAL REGION

Michael MacDonald Hydrogeologist

MM:ns

c: Jolene Meissner, ECCI Tom Hvizdak, Wisconsin Rapids

Bill Evans, Eau Claire

(C:\LU\CREOLA.CLO)

